

**STREAM WATER BLACKENING BY EFFLUENT DISCHARGE OF A
YARN DYEING INDUSTRY**

A PROJECT REPORT PRESENTED

BY

PRIYANTHA LAKSHMEN FERNANDO

to the

POSTGRADUATE INSTITUTE OF SCIENCE

in partial fulfillment of the requirement

for the award of the degree of

MASTER OF SCIENCE

of the

UNIVERSITY OF PERADENIYA

SRI LANKA

January 2002

ABSTRACT**STREAM WATER BLACKENING BY EFFLUENT DISCHARGE OF A YARN
DYEING INDUSTRY**

Priyantha Lukshmen Fernando
M.Sc. in Industrial chemistry
Postgraduate Institute of Science
University of Peradeniya

This project report describes the causes for the blackening of a water stream due to effluent discharge of a yarn dyeing industry. Although the discharged treated effluent is initially colourless when it enters the water stream, significant blackening is observed after discharge. Introductory chapter gives a general description of the industrial water pollution and about the textile sector and related processes. Experimental part consists of qualitative and quantitative chemical analysis of black substance, effluent and soil. Formation of iron sulphide in the stream is the cause for blackening. Generation of dissolved sulphide by the biological reduction of sulphate caused iron sulphide formation in the stream. High biological oxygen demand (BOD), excessive sulphate content of effluent and high iron content in soil are causative factors. These factors were further confirmed by simulation. Reduction of BOD and sulphate content in discharging effluent are suggestions for the prevention.